

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	)	
TAKAHIRO YAJIMA ET AL.	:	Examiner: J.J. Maldonado
Appln. No.: 09/900,043	:	Group Art Unit: 2823
Filed: July 9, 2001	:	Certificate
For: THIN FILM FORMATION METHOD	: )	JAN 2 5 2005 of Correction
U.S. Patent No.: US 6,800,539 B2	:	of Collection
Issued: October 5, 2004	:	January 13, 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

# CERTIFICATE OF CORRECTION \_\_\_\_\_UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Peter Saxon

Attorney for Patentees Registration No. 24,947

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

NY\_Main 465969v1

# Staple Here Only! NIT WILL S. WILL S.

### UNITED STATES PATENT AND TRADEMARK OFFICE

# **CERTIFICATE OF CORRECTION**

PATENT NO.

US 6,800,539 B2

DATED

October 5, 2004

INVENTOR(S) :

TAKAHIRO YAJIMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 27, "Mark ▼" should read --Mark ▲--.

COLUMN 7:

Line 42,"Mark ▼" should read --Mark ▲--.

**COLUMN 8:** 

Line 55, "(Mark ▼" should read --(Mark ▲--; and Line 59, "(Mark ▼" should read --(Mark ▲--.

COLUMN 10:

Line 38, "1000 sccm." should read --10000 sccm.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY\_Main 465969v1 PATENT NO. <u>US 6,800,539 B2</u>

No. of add'l. copies @ 30¢ per page

=>

# Staple Here Only!

### UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.

US 6,800,539 B2

**DATED** 

October 5, 2004

INVENTOR(S) :

TAKAHIRO YAJIMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 27, "Mark ▼" should read --Mark ▲--.

COLUMN 7:

Line 42,"Mark ▼" should read --Mark ▲--.

COLUMN 8:

Line 55, "(Mark ▼" should read --(Mark ▲--; and Line 59, "(Mark ▼" should read --(Mark ▲--.

COLUMN 10:

Line 38, "1000 sccm." should read -- 10000 sccm.--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) NY Main 465969v1 PATENT NO. US 6,800,539 B2

No. of add'l. copies @ 30¢ per page

